

ООО «Гудьер Раша»
ул. Садовая-Самотечная,
24/27
127051 Москва
Россия



Телефон:
7095-720 6655

Факс:
7095-720 6632

www.goodyear.com

КОГО ЭТО МОЖЕТ КАСАТЬСЯ

В соответствии с сервисным бюллетенем PSB # 2003-05 и 06 (см. извлечения ниже) все легковые и легкогрузовые шины могут быть отремонтированы только в случае прокола в протекторной части, ограниченной внешними канавками.

Не допускается ремонт за внешними канавками (в плечевой зоне протектора) и на боковинах шины.

Product Service Bulletin

Important Information To Better Service Your Customers

PSB #2003-05

SUBJECT: Repairing of Passenger and Light Truck Tires that are less than H speed-rated (less than 130 mph)

PSB #2003-06

SUBJECT: Puncture Repairing and Retreading of tires that are "H" Speed-Rated and higher (equal to or greater than 130 mph) includes Goodyear EMT & Dunlop DSST tires

I. DETAILED POLICY:

- A. The puncture must be confined to the tread area only.
(See "Repair Area", Item II-C).
- B. Restrictions on the number and size of repairs must be followed.
(See "Puncture Repair Limits and Repair Area", Item II B.)
- C. A detailed repair procedure must be followed.
(See "Repair Procedure", Item II E.)

II. REPAIR PROCEDURE

C. REPAIR AREA

Repairing is limited to the tread area only within the outside grooves. No repairs are allowed in the tread area beyond the outside grooves or in the sidewall area of the tire.

THE GOODYEAR TIRE & RUBBER COMPANY
PRODUCT SERVICE DEPARTMENT

С уважением
ООО «Гудьер Раша»